


GSM SERVICE SUPPOR	2005.8.23
Level 3 Signal Flow	Rev. 1.0
C139 EU	Rev. 0C
TC Chen	Page 1 of 2

	EARP
	EARN



LED+			VBACKUP	VRIO_2.8V	CLK32K_OUT	PAENA	APC
------	--	--	---------	-----------	------------	-------	-----

EAR_DETECT	MICBIAS	HSMICBIAS	VRMEM_2.8V	VRRAM_2.8V	CLK13M_OUT	DLPWR	AFC
------------	---------	-----------	------------	------------	------------	-------	-----

(C)	EARP
(D)	EARN
(E)	BUZER
(F)	HSO
(G)	VIBRATOR
(H)	HSMICIP
(I)	MICIP
(J)	MICIN
(K)	RXI
(L)	RXO

GSM SERVICE SUPPOR	2005.8.23
Level 3 Signal Flow	Rev. 1.0
C139 EU	Rev. 0C
TC Chen	Page 2 of 2