

Ⓒ	EARP
Ⓓ	EARN


GSM Service Support	2004.8.12
Level 3 Signal Flow	Rev.1.0
C155	Rev.1.0
Jay Chen	Page 1 of 2

LEDKEY_EN

VBACKUP

VRIO_2.8

CLK32K_OUT



Ⓞ	EARP		
Ⓧ	EARN	Ⓧ	MICIP
Ⓛ	HSO	Ⓧ	MICIN
Ⓞ	VIBRATOR	Ⓧ	RXI
Ⓧ	HSMICIP	Ⓧ	RXQ

MICBIAS	VRMEM_2.8V	VRRAM_2.8V	CLK13M_OUT	DLPWR
---------	------------	------------	------------	-------

GSM Service Support	2004.8.12
Level 3 Signal Flow	Rev.1.0
C155	Rev.1.0
Jay Chen	Page 2 of 2